

# ***Engineering Bulletin***

**RF TECHNOLOGY Pty Ltd**  
PO BOX 328 Wahroonga NSW 2076  
Australia  
Ph : +61 2 9476 5929  
Fax : +61 2 9476 4932

***ECLIPSE***  
**Engineering Bulletin**  
No: 

EB-0604
---------

**Product : Battery Charger / Change Over**

**Topic : Faulty Relays**

**Date : 14/09/2006**

---

Faulty relays were found in recent batch of Battery Charger/Change Over (BC-CH1) product.

Please check relay part number on the BC-CH1 PCB, the correct part number should be: TRKP-M-S-Z1

If the faulty relay (part number: TRKP-L-S-H1) is mounted on the PCB, please report to RF Technology, we will ship the replacement BC-CH1 to you.

Guang H Lou  
Chief Engineer